



# Proposed Miami Bridge Improvements

## We Have to do Something!



K0999 06-14-05  
Large hole rusted thru gusset plt @ L-18' E side



K0999 06-15-05  
Flat plt brgs shifted 1" N @ bt 11



K0999 06-14-05  
SIP forms rusted thru out bridge



K0999 06-15-05  
13" x 2" hole in web  
of 7th flr bm N of pier 7 E side



K0999 06-14-05  
Small hole in E OS strgr @ L-16'



K0999 06-15-05  
Small hole in 6th flr bm N of pier 7 E side



K0999 08-08-07  
os ends of flbs w/ hvy pk rust &  
sect loss span 3



K0999 08-08-07  
Several flbs w/hvy pk rust & sect loss  
throughout spans 7-14 E side



K0999 06-14-05  
Hole rusted thru gusset plt @ L-18' E side



K0999 08-08-07  
Sway bracing w/ pk rust & sect loss @  
btm corners N end span 3 from S



K0999 06-15-05  
SIP forms rusted thru @ bt 8



K0999 08-08-07  
Sway bracing w/ pk rust & sect loss @  
btm corners N end span 3 from S